## TRANZ-FORMER - MODELS 09092, 09093, 09095 - MANUAL CORRECTIONS AND CHANGES REVISION 2-14-2014 and REVISION 9-17-2015

PAGE#	DWG.#	ITEM	PART # LISTED	NEW PART #	DESCRIPTION	CORRECTION	DATE CORRECTED	P.T.
	3	N/A	N/A	N/A	DRAWING # 3 IS FOR THE REAR ROLL ASSEMBLY ONLY			
					CHAIN, ROLL DRIVE #60 HEAVY, 47 PITCH, REAR ROLL			
9	3	18	0309040-N (QTY. 3)	0309100-N	ASSEMBLY (QTY. 2)	INCORRECT PT. # LISTED	10/27/2014	Х
			NOT LISTED	0309101-N	CHAIN, ROLL DRIVE # 60H, 45 PITCH, FRONT ROLL ASSEMBLY (QTY. 1)	FRONT ROLL ASSEMBLY NOT SHOWN	10/27/2014	х
16	10	7	0308041-N	N/A	PUSH-PULL CABLE	ITEM # 7 AS LISTED IS ACTUALLY ITEM # 10.	7/22/2015	
16	10	10	0308041-N	N/A	CHOKE CABLE (PEDAL TO PUMP)	THIS IS A PUSH-PULL CABLE, NOT A CHOKE CABLE.	10/27/2014	х
42	7	42	0200042 N	- 1-	CHOKE CARLE (FOOT REPAIL TO RUMAR)	THIS IS A PUSH-PULL CABLE, NOT A CHOKE	7/22/2015	
13	/	12	0308043-N	n/a	CHOKE CABLE (FOOT PEDAL TO PUMP)	CABLE.	7/22/2015	
					HYD. CYLINDER, FRONT WHEEL, LOCK NUT, HYD CYL,	THE NUTS AND BALL JOINT ARE NOW		
12	6	14, 15 & 16	0330176, 0338110, 0303095	0230260	FRONT WHEEL & BALL JOINT, HYD CYL	WELDED TO THE HYDRAULIC CYLINDER	9/23/2015	X
						DESCRIPTION SHOULD READ MASTER DISCONNECT/ROLL TRANSPORT SWITCH - QTY.2, NOT 1 AS BOTH SWITCHES ARE THE SAME. THE ITEM # IS NOT CALLED OUT FOR		
18	12	8	0315408	NUMBER IS CORRECT	MASTER DISCONNECT SWITCH ON/OFF	THE ROLL TRANSPORT SWTICH.	8/5/2016	х